
























PL: INSTRUKCJA MONTAŻU
EN: ASSEMBLY MANUAL
CZ: PŘÍRUČKA PRO MONTÁŽ
SK: PRÍRUČKA PRE MONTÁŽ
DE: MONTAGEANLEITUNG
SR: UPUTSTVO ZA INSTALACIJU
NL: MONTAGE-INSTRUCTIES






Ax26  Ø8x35mm	Bx18  Ø3,5x16mm	Cx6  Ø15x20mm	Dx28  Ø21mm	Ex32  Ø15x12mm
Fx28  Ø5x38mm	Hx54  26mm	Jx2  75x28x16 mm	Kx6  Ø35mm, 90°	Lx12  Ø5x16mm
Mx14  22x10mm	Nx2  Ø8x60mm	Ox4  Ø8x1,5mm	Px2  Ø8x35mm	Qx2  Ø7x70mm
Rx2  Ø4x30mm				






No.	L[mm]	W[mm]	H[mm]	PSC BOX
1	1940	500	15	1 1/2
2	1940	500	15	1 1/2
3	903	530	22	1 2/2
4	870	500	15	1 2/2
5	869	60	15	1 2/2
6	471	427	15	2 2/2
7	1865	471	15	1 1/2
8	1876	380	15	2 1/2
9	1940	50	22	1 1/2
10	1940	50	22	1 1/2
11	471	427	15	3 2/2
12	1900	447	2,5	2 1/2
13	1865	70	28	1 1/2
14	420	22	15	1 2/2





1







2






3








4






5






6



7




8



9


I

Fx8





Ø 5x3 8mm

Kx6




Ø35mm, 90°






II

K1

K2




F





10


Ex8






Ø15x12mm






E






11






12



13




14




15

Hx54






26mm

Mx14




22x10mm





$A=B \equiv 90^\circ$

16


Ax4






Ø 8x3 5mm












17



18




19




20

Bx2



Ø3,5x16mm

Lx12







Ø5x16mm

Px2




Ø8x35mm




21

Bx12







Ø3,5x16mm





K2x6





Ø35mm, 90°





22




23








I




II




III





I




II




III



I



II



III

