

























PL: INSTRUKCJA MONTAŻU
EN: ASSEMBLY MANUAL
CZ: PŘÍRUČKA PRO MONTÁŽ
SK: PRÍRUČKA PRE MONTÁŽ
DE: MONTAGEANLEITUNG
SR: UPUTSTVO ZA INSTALACIJU
NL: MONTAGE-INSTRUCTIES
PT: MONTAGEM DE INSTRUÇÃO
HR: SASTAVLJANJE UPUTE




A1 x 30  Ø8x35mm	B1 x 30  Ø5x38mm	C1x30  Ø15x12mm	F2x12  40mm	G1x67  26mm
Jx12  Ø21mm	K1 x 12  Ø6,4x50mm	N2x1  4mm HEX	T4x1  75x28x16 mm	P2x6  350mm
W1 x 20  Ø3,5x13mm	W2x24  Ø3,5x16mm	W5x14  Ø4x30mm	Y1x6  Ø8x1,5mm	Y5x6  Ø15x20mm



Np.	L[mm]	W[mm]	H[mm]	PCS	BOX
2	350	120	15	3	1/1
3	350	120	15	3	1/1
4	336	120	15	3	1/1
5	360	355	2,5	3	1/1
6	395	200	15	1	1/1
7	503	430	22	1	1/1
8	470	371	15	1	1/1
9	470	400	15	1	1/1
10	469	60	15	1	1/1
10	470	70	28	2	1/1
11	470	70	28	1	1/1
12	1000	50	22	1	1/1
13	1000	50	22	1	1/1
14	1000	400	15	1	1/1
15	1000	400	15	1	1/1
16	496	960	2,5	1	1/1


1

A1x8








Ø8 x35mm


B1x12



Ø 5x3 8m m





A1





14

B1






15

2




3




4

F2x12






40mm

W2x24




Ø3,5x16mm



5


P2x6



35.0 mm




$P2 = P2-a + P2-b$




6

P2-a x 6







35 0 mm



W5 x 12











Ø4x30mm





7





8




9




10




11




x2₁₀





12




C1






13






14





15





16



17




18





19



G1x28



26mm




$A=B \equiv 90^\circ$




20

W5x2






Ø 4x3 0mm









Y5x6



Ø15x20mm




21





22

B1x6




Ø 5x3 8mm





23



A1x6




Ø 8x3 5mm




24





x3
C1



25




x3





26


G1x39




26mm



$A=B \equiv 90^\circ$



x3



27

Jx6



Ø21 mm

P2-bx6




350mm


W1 x 12









Ø3,5x13mm






x3




28



29



x3



30

