



























PL: INSTRUKCJA MONTAŻU
 EN: ASSEMBLY MANUAL
 CZ: PŘÍRUČKA PRO MONTÁŽ
 SK: PRÍRUČKA PRE MONTÁŽ
 DE: MONTAGEANLEITUNG
 SR: UPUTSTVO ZA INSTALACIJU
 NL: MONTAGE-INSTRUCTIES
 PT: MONTAGEM DE INSTRUÇÃO
 HR: SASTAVLJANJE UPUTE





A1 x 32  Ø8x35mm	B1 x 30  Ø5x38mm	C1x30  Ø15x12mm	E1x8 K2DP  Ø5x16mm	E9x8 K2D 
H7x1  139 5m m	G1 x 80  26mm	Jx14  Ø21mm	K1x16  Ø6,4x50mm	N2x1  4mm HEX
P2x6  350mm	T4x2  75x28x16 mm	W1 x 30  Ø3,5x13mm	W2x12  Ø3,5x16mm	W5x2  Ø4x30mm
Y1x10  Ø8x1,5mm	Y5x8  Ø15x20mm	Z6x4  Ø35mm, 90°		



x3


Np.	L[mm]	W[m m]	H[mm]	PCS	BOX
2	350	120 120	120	3	2/4
3	350	354 200	120	3	1/4
4	420	430 400	15	3	1/4
5	446	70	2,5	3	1/4
5	480	70	15	2	2/4
6	480	60	15	1	1/4
7	1403	50	22	1	1/4
8	1370	50	15	1	1/4
8	474	400	200	2	1/4
9	1370	395/390	5285	1	1/4
10	1369		15	1	1/4
11	765		22	1	2/4
12	765		22	1	2/4
13	765		15	1	2/4
14	765		15	1	2/4
15	43 1/ 43			2	3/4
16	2 689			1	2/4
17	689	400	15	1	2/4
18	1397	400	15	1	1/4
19	1397	361	2,5	1	1/4
20	670	361	2,5	2	4/4
		405	18/15		

1




2

A1x4




Ø 8x3 5mm

B1x4



Ø5x38mm

P2-a x 6







350mm



W1 x 12



Ø3,5x13mm




3





8

x2



4




16

17



C1

8


8



5




6



7

K1x4





Ø6,4x50mm

N2x1




4mm HEX








8



A1x2






Ø 8x3 5mm














14







15



16




17



$A=B \equiv 90^\circ$

18

G1x12






26mm

Y5x8




Ø15x20mm

G1




19

T4x2















75x28x16 mm

W2x4




Ø 3,5x16mm



20

W2x8




Ø3,5x16mm

Y1x4






Ø8x1,5mm

Z6-b x 4






Ø35mm, 90°





x2



21



22





23






x3

24





x3

25



x3


26



x3




27

G1x36




26mm

G1




$A=B \equiv 90^\circ$



x3

28

Jx6



Ø21 mm

P2-bx6





350mm

W1 x 12



Ø3,5x13mm



x3


29

Y1x6






Ø8x1,5mm

I



II



30

Jx8




Ø21 mm






31

W1x6



Ø 3,5x13mm



32

