




PL: INSTRUKCJA MONTAŻU

EN: ASSEMBLY MANUAL

CZ: PŘÍRUČKA PRO MONTÁŽ

SK: PRÍRUČKA PRE MONTÁŽ




















DE: MONTAGEANLEITUNG






SR: UPUTSTVO ZA INSTALACIJU

NL: MONTAGE-INSTRUCTIES

PT: MONTAGEM DE INSTRUÇÃO

HR: SASTAVLJANJE UPUTE

 				
A1 x 24	B1x24	C1x20	C2x4	E1x12
 Ø8x35mm	 Ø5x38mm	 Ø15x12mm	 Ø12x10mm	 Ø5x16mm
F2x8	G1 x 44	Hx1	J1 x14	P2x4
 40mm	 26mm	 1915mm	 Ø21mm	 350mm
T4x2	U3x4	W1 x 12	W2x20	W5x10
 75x28x16 mm	 92x33mm	 Ø3,5x13mm	 Ø3,5x16mm	 Ø4x30mm
X2x8	Y1x4	Y5x7		
 M4x1 6m m	 Ø8x1,5mm	 Ø15x20mm		



No	L[mm]	W[mm]	H[mm]	PCS	BOX
W029	1446	100	12	2	2/3
001	775	188	18	1	1/3
101	1940	400	15	1	2/3
102	1940	400	15	1	2/3
201	902	430	36	1	1/3
301	850	400	15	1	2/3
302	850	400	15	3	2/3
303	850	400	15	1	1/3
401	849	60	15	1	1/3
5109	730	351	2,5	2	2/3
5111	1915	438	2,5	2	2/3
601	1940	50	22	2	2/3

[illegible]

A1x4		Ø8x35mm
P2x4		350mm
W1x8		Ø3,5x13mm

I

II

P2

P2-a

P2-b

A1

W1

P2-b

W029

W1

P2-b

W1

x2





A1

W029






5109

x2






3



4






5






x2




6



7




8



9

A1x8






Ø 8x 35mm

C1x8




Ø15x12mm




10

A1x8



Ø 8x3 5mm

B1x8





Ø5x38mm




C1 x 12





Ø15x12mm




11








14





15






16








17




A=B







18






19







20







21



22




23




24

T4x2














75x28x16 mm


W2x4




Ø 3,5x16 mm





25






I




II



26



I



II

