




PL: INSTRUKCJA MONTAŻU

EN: ASSEMBLY MANUAL


CZ: PŘÍRUČKA PRO MONTÁŽ

SK: PRÍRUČKA PRE MONTÁŽ






DE: MONTAGEANLEITUNG

SR: UPUTSTVO ZA INSTALACIJU


NL: MONTAGE-INSTRUCTIES









Ax40 $\varnothing 8 \times 35 \text{ mm}$	Bx28 $\varnothing 3,5 \times 16 \text{ mm}$	Cx12 $\varnothing 15 \times 20 \text{ mm}$	Dx40 $\varnothing 21 \text{ mm}$	Ex44 $\varnothing 15 \times 12 \text{ mm}$
Fx36 $\varnothing 5 \times 38 \text{ mm}$	Hx92 26mm	Ix32 22x10mm	Jx2 75x28x16 mm	Kx12 $\varnothing 5 \times 16 \text{ mm}$
Lx6 $\varnothing 8 \times 1,5 \text{ mm}$	Mx4 $\varnothing 8 \times 35 \text{ mm}$	Ox4 n35 , ZK0	Px4 50x40, H=2	Qx6 $\varnothing 35 \text{ mm}, 90^\circ$
Rx4 $\varnothing 7 \times 70 \text{ mm}$	Sx4 $\varnothing 8 \times 60 \text{ mm}$			



No.	L[mm]	W[mm]	H[mm]	PSC BOX
1	1940	500	15	1 1/3
2	1940	500	15	1 1/3
3	1663	530	22	1 2/3
4	1630	500	15	1 2/3
5	1464	471	15	1 2/3
6	1368	471	15	2 2/3
7	1365	471	15	1 1/3
8	1365	471	15	1 1/3
9	1405	1876	15	2 3/3
10	1495	1876	15	1 3/3
11	1464	471	15	3 2/3
12	1588	1900	2,	2 3/3
13	1865	70	5	2 3/3
14	1629	60	28	2 2/3
15	1940	50	15	1 1/3
16	1940	50	22	1 1/3
17	1480	1900	22	1 3/3
18	1560	23	2,	2 2/3
			5	




1




2

Ax12






Ø 8x35mm

Kx12




Ø5x16mm






3






Fx8







Ø 5x38mm








4






5






6






7




8






9






10








11






12






13





14



15




16




17

Cx12






Ø15x20mm


Ex8




Ø15x12mm




3





18



19




$A=B \equiv 90^\circ$





20

Hx60




26mm




21

Bx4











Ø3,5x16mm


Jx2



75x28x16 mm




22





23

Fx8




$\varnothing 5 \times 3.8 \text{ mm}$




24

Bx12





Ø3,5x16mm


Qx6




Ø35mm, 90°






I







II




III






25







26






27





28
















29



30



31



32

