




PL: INSTRUKCJA MONTAŻU

EN: ASSEMBLY MANUAL

CZ: PŘÍRUČKA PRO MONTÁŽ

SK: PRÍRUČKA PRE MONTÁŽ


DE: MONTAGEANLEITUNG





















SR: UPUTSTVO ZA INSTALACIJU





NL: MONTAGE-INSTRUCTIES

PT: MONTAGEM DE INSTRUÇÃO



HR: SASTAVLJANJE UPUTE







A1 x 24  Ø8x35mm	B1 x 24  Ø5x38mm	C1x20  Ø15x12mm	C2x4  Ø12x10mm	E1x12  Ø5x16mm
G1 x 40  26mm	Hx2  1915mm	J1 x20  Ø21mm	K1x12  Ø6,4x50mm	N2x1  4mm HEX
P2x4  350mm	T4x2  75x28x16 mm	U1x2  Ø33mm	U3x2  92x33mm	W1 x20  Ø3,5x13mm
W2 x16  Ø3,5x16mm	W5x2  Ø4x30mm	X2x4  M4x16mm	X4x2  M4x25mm	Y1x7  Ø8x1,5mm
Y5x6  Ø15x20mm	Z6x6  Ø35mm, 90°			








No	L[mm]	W[mm]	H[mm]	PCS	BOX
W002	1049	100	12	1	1/3
099	395	189	18	1	2/3
0100	395	189	18	1	2/3
0101	1678	395	18	1	2/3
0102	1678	395	18	1	2/3
1214	1940	400	15	1	2/3
1215	1940	400	15	1	2/3
1222	173	400	22	1	1/3
1223	173	400	22	1	1/3
1226	173	400	15	1	1/3
239	902	430	36	1	1/3
3141	870	400	15	1	1/3
3142	870	400	15	1	1/3
3143	870	400	15	3	1/3
442	869	60	15	1	1/3
516	336	351	2,5	2	2/3
5115	1915	299	2,5	3	2/3
630	1940	50	22	1	2/3
648	1940	50	22	1	2/3








3






4





5




x2





9



10



11



12

P2-a x 4









350mm




W1 x 8





Ø3,5x16mm




13




14





15



4mm HEX




16




17

G1x40





26mm




Hx2




1915mm






$A=B \equiv 90^\circ$






18




19





20







21





22





23




24




25






I



II




26



I




II




27

14x2








75x28x16 mm

W2x4



Ø 3,5x16mm



28

