




























PL: INSTRUKCJA MONTAŻU
EN: ASSEMBLY MANUAL
CZ: PŘÍRUČKA PRO MONTÁŽ
SK: PRÍRUČKA PRE MONTÁŽ
DE: MONTAGEANLEITUNG
SR: UPUTSTVO ZA INSTALACIJU
NL: MONTAGE-INSTRUCTIES
PT: MONTAGEM DE INSTRUÇÃO
HR: SASTAVLJANJE UPUTE




A1 x 30  Ø8x35mm	B1 x 30  Ø5x38mm	C1x30  Ø15x12mm	E1x4  Ø5x16mm	E9x8 
G1 x 84  26mm	H5x1  1899mm	Jx16  Ø21mm	K1x12  Ø6,4x50mm	N1x1 
N2x1  4mm HEX	P2x2  350mm	T4x2  75x28x16 mm	W1x10  Ø3,5x13mm	W2x20  Ø3,5x16mm
W5x2  Ø4x3 0m m	Y1x8  Ø8x1,5mm	Y5x6  Ø15x20mm	Z6x8  Ø35mm, 90°	



Np.	L[mm]	W[mm]	H[mm]	Pcs	BOX
2	350	120	15	1	1/4
3	350	120	15	1	1/4
4	721	120	15	1	2/4
5	746	358	2,5	1	2/4
6	794	200	15	1	2/4
7	903	430	22	1	2/4
8	870	371	15	1	2/4
9	870	400	15	1	2/4
10	869	60	15	1	2/4
11	1900	447	2,5	2	1/4
12	870	70	28	2	2/4
13	870	371	15	1	2/4
14	870	371	15	1	2/4
15	1940	400	15	1	1/4
16	1940	50	22	1	1/4
17	1940	50	22	1	1/4
18	399	223	15	1	1/4
19	399	223	15	1	1/4
20	868	395	5	2	3/4
21	1070	395	18	2	4/4
22	540	395	15	2	1/4


1

A1x8





Ø 8x3 5mm



B1 x 12









Ø5x38mm



B1




A1




2

B1x8







Ø 5x3 8mm

Z6x8




Ø35mm, 90°


B1




I




II





Z6-a





Z6-b






3






4






5






6




7




8






9



$P2 = P2-a + P2-b$




10



11

K1x8





Ø6,4x50mm

N2x1




4mm HEX





12




B1x4






Ø 5x3 8mm







13







14



15




16




17

T4x2














75x28x16 mm




W2x4




Ø 3,5x16mm



18




19



20

W2x16






Ø3,5x16mm





Z6-bx8






Ø35 mm, 90°






21






22






23





24



25





26








G1




$A=B \equiv 90^\circ$




27




28



I



II





29


W1 x 2




Ø3,5x13mm





I



II



30



31

