
























PL: INSTRUKCJA MONTAŻU
EN: ASSEMBLY MANUAL
CZ: PŘÍRUČKA PRO MONTÁŽ
SK: PRÍRUČKA PRE MONTÁŽ
DE: MONTAGEANLEITUNG
SR: UPUTSTVO ZA INSTALACIJU
NL: MONTAGE-INSTRUCTIES
PT: MONTAGEM DE INSTRUÇÃO
HR: SASTAVLJANJE UPUTE




A1 x 28  Ø8x35mm	B1 x 30  Ø5x38mm	C1x30  Ø15x12mm	E1x4  Ø5x16mm	E9x8 
G1 x 66  26mm	Jx16  Ø21mm	K1 x 12  Ø6,4x50mm	N2x1  4mm HEX	P2x2  350mm
T4x1  75x28x16 mm	W1 x 10  Ø3,5x13mm	W2x10  Ø3,5x16mm	W5x2  Ø4x30mm	Y1x5  Ø8x1,5mm
Y5x6  Ø15x20mm	Z6x4  Ø35mm, 90°			



Np.	L[mm]	W[mm]	H[mm]	PCS	BOX
2	503	430	22	1	2/4
3	470	371	15	1	1/4
4	470	371	15	1	2/4
5	470	400	15	1	2/4
6	1940	400	15	1	1/4
7	1940	400	15	1	1/4
8	1900	497	2,5	1	1/4
9	1940	50	22	1	1/4
10	1940	50	22	1	1/4
11	469	60	15	1	2/4
12	399	223	15	1	2/4
13	399	223	15	1	2/4
14	470	70	28	2	2/4
15	350	120	15	1	1/4
16	350	120	15	1	1/4
17	321	120	15	1	2/4
18	395	200	15	1	1/4
19	358	349	2,5	1	2/4
20	395	540	15	1	1/4
21	1070	395	18	1	4/4
22	468	395	5	2	3/4
	470	371	15	1	1/4


1

A1x8












Ø 8x3 5mm

B1 x 12




Ø5x38mm





2


B1x8




Ø 5x3 8mm









3







I









II






4






5






6






7




8




9






10



$P2 = P2-a + P2-b$




11



12

K1x8





Ø6,4x50mm

N2x1




4mm HEX





13

B1x4







Ø 5x3 8mm




B1








14








15



16




17



18

T4x1














75x28x16 mm





W2x2



Ø 3,5x16mm



19




E9




E1

20




21

W2x8







Ø3,5x16mm





Z6-bx4








Ø35 mm, 90°






22






23





24







25








26




27




28




29



I



II





30


W1 x 2




Ø3,5x13mm





I



II



31



32

