






























PL: INSTRUKCJA MONTAŻU
EN: ASSEMBLY MANUAL
CZ: PŘÍRUČKA PRO MONTÁŽ
SK: PRÍRUČKA PRE MONTÁŽ
DE: MONTAGEANLEITUNG
SR: UPUTSTVO ZA INSTALACIJU
NL: MONTAGE-INSTRUCTIES
PT: MONTAGEM DE INSTRUÇÃO
HR: SASTAVLJANJE UPUTE







A1 x 20  Ø8x35mm	B1 x 22  Ø5x38mm	C1x20  Ø15x12mm	C2x2  Ø12x10mm	E1x12  Ø5x16mm
G1 x 34  26mm	Hx1  1915mm	J1 x16  Ø21mm	K1x8  Ø6,4x50mm	N2x1  4mm HEX
P2x2  350mm	T4x1  75x28x16 mm	U1x1  Ø33mm	U3x1  92x33mm	W1x10  Ø3,5x13mm
W2x8  Ø3,5x16mm	W5x2  Ø4x30mm	X2x2  M4x16mm	X4x1  M4x25mm	Y1x4  Ø8x1,5mm
Y5x6  Ø15x20mm	Z6x3  Ø35mm, 90°			




No	L[mm]	W[mm]	H[mm]	PCS	BOX
0102	1678	395	18	1	2/3
0103	395	189	18	1	2/3
1214	1940	400	15	1	2/3
1215	1940	400	15	1	2/3
1222	400	173	22	1	1/3
1223	400	173	22	1	1/3
237	502	430	36	1	1/3
3132	470	400	15	3	1/3
3135	470	400	15	1	1/3
3138	470	400	15	1	1/3
441	469	60	15	1	1/3
5112	1915	248	2,5	2	2/3
516	351	336	2,5	1	2/3
629	1940	50	22	1	2/3
630	1940	50	22	1	2/3
W002	1049	100	12	1	1/3







1








2






3



4




5




6

W2x6




Ø3,5x16mm

Z6x3






Ø35mm, 90°

I




II





7

B1x4




Ø 5x3 8mm





8

A1x2




Ø 8x3 5mm




9

A1x8



Ø 8x3 5mm

B1x8




Ø5x38mm

C1 x 12





Ø15x12mm

E1x12




Ø5x16mm




10

B1x8




Ø5x38mm

Z6-a x 3




50x40, H=4



11

A1x8




Ø8x35mm

C1x8




Ø15x12mm



12

P2-a x 2








350 mm


W1 x 4



Ø 3,5 x 13 mm



13




1215

630

1214

629

14





1214

3138



3132

1215

15




16




17

G1x34









26mm


Hx1






1915mm






18




19





20






21






22





23







24



25



26



27

T4x1








75x28x16 mm

W2x2



Ø 3,5x16mm



28

